

STANLEY

Hydraulic Tools

HOTLine

Date April 18, 2003

New Diamond Saw Chain

Hotline No. 04182003

Get on top of your game with the **Pinnacle** and **Ultra** saw chain.

Continuing product improvement has brought about this new pointed top chain and reduced the selection of sealed saw chain.

The pointed top design creates a fast-opening segment which means the chain does not need to break in to begin cutting. This new design is cutting right from the start. The shape has a leading edge that is better protected by the bumper; it will not snag, a cause of broken segments. The volume of the new segment is the same as that of the rectangular segment, so the cutting capacity is the same.


With this new design we have reduced the saw chain selection to only two chains - the **Pinnacle** and the **Ultra**.

Pinnacle, the highest grade saw chain, will cut all materials. This one cuts the very hard, the soft, and the abrasive materials. It replaces the DC05 saw chain with the pointed segment and a single bumper leading the segment.

Ultra, a hybrid grade combining the value of the CC chain with the feature of the double-bumper chain, will cut most materials from the medium hard, to the abrasive, to the soft. It is a double-bumper style chain which can be installed without concern for saw chain direction.

For comparison, the illustration shows the **Pinnacle** and **Ultra** segments and the current saw chain segment grades they will replace in applications:


DC05

Pinnacle

DB25

DC40

CC

Ultra

The choices are simple and the performance is outstanding. Get your saw, install the chain, connect the water, hook up the hydraulics, and take a cut. The latest sealed saw chain gets you to the hole.

Pinnacle and Ultra - - - - the only choices.

The table below shows, in addition to the new saw chain, the discontinued saw chain. The 8" Bar and 21-link DS06 saw chain and the 12" Bar and 27-link DS11 saw chain are being discontinued with no replacement. The **Pinnacle** and **Ultra** saw chains should be ordered in place of the other discontinued saw chains.

Saw Model	Type-drive links	Part No.	Part No.	Type-drive links	List \$	Disc Code	
DS06	DC05-21	40329	Discontinued				
	DB25-21	58502	Discontinued				
	DC40-21	41864	Discontinued				
	CC-21	40347	Discontinued				
	DC05-25	40331	Replace with	56800	Pinnacle-25	\$ 625.00	L
	DB25-25	56762	Replace with	56799	Ultra-25	\$ 360.00	L
	DC40-25	41865					
	CC-25	40348					
	DS11	DC05-27	40333	Discontinued			
		DB25-27	58503	Discontinued			
DC40-27		40344	Discontinued				
CC-27		40349	Discontinued				
DC05-32		40335	Replace with	56803	Pinnacle-32	\$ 795.00	L
DC05-37		40337	Replace with	58632	Pinnacle-37	\$ 925.00	L
DB25-32		58504	Replace with	56801	Ultra-32	\$ 445.00	L
DC40-32		40345					
CC-32		40350					
DB25-37		58505	Replace with	56802	Ultra-37	\$ 510.00	L
DC40-37		40346					
CC-37		40351					

The discontinued saw chains will be available through May, or as long as supplies last. The **Pinnacle** and **Ultra** saw chains will be available and in stock the middle of May.